

**IN THE DRAWINGS**

The drawings were objected to under 37 CFR 1.83(a) because they failed to show the following items as described in the specification: Receive message ring 112 in Fig. 1A, 1B, 1C, 1D; Best-effort message ring 122 in Fig. 1A, 1B, 1C, 1D, 6, 7; Shaped schedule wheel 124 in Fig. 1A, 1B, 1C, 2, 4, 6, 7; and Link layer component(s) 222 in Fig. 5. A total of 8 sheets of replacement drawings have been submitted herewith.